





BUILDING SPECIFICATIONS:

Building Name: Building I

Building Type: Type II - Medium Distribution

Multi-Tenant:YesSubmarket:NorthCounty:HamiltonTownship:Washington

Total Building Size: 50,000

Construction Status: Existing

Yr/Qtr Built: 1997 1

Ceiling Height: 24

Bays: 33' x 150'
Docks/Doors: 4/2
Rail: No
Acres: 6.500
Sprinkler: Wet

Exterior Construction: Split Face Block & Metal Roof: Metal Standing Seam

Floor Composition: 6" Concrete

Comments:

LISTING:

UTILITIES:

Power: 400amp, 120/208/3phase

Gas: Westfield Gas
Water: Hamilton Co.
Sewer: Hamilton Co.
Heat: Gas Fired

AVAILABILITY:

Max. SF Available: 0
Min. SF Available: 0
Sublease SF Available: 0

CONTACTS: Colliers Turley Martin Tucker

J. Bart Book, SIOR (317) 634-6363

Owner Company: Storage Solutions
Owner: Storage Solutions

Property Mgmt:

Disclaimer: The information contained herein was obtained from sources we consider reliable. We cannot be responsible, however, for errors, omissions, prior sale, withdrawal from the market, or change in price. Seller and broker make no representation as to the environmental condition of the property and recommend purchaser's independent investigation.

Inventory ID:





BUILDING SPECIFICATIONS:

Building Name: Building III

Building Type: Type II - Medium Distribution

Multi-Tenant: Yes **Submarket:** North **County:** Hamilton **Township:** Washington

Total Building Size: 64,800 **Construction Status:** Existing Yr/Qtr Built: 2001 3

Ceiling Height: 24

Bays:

Docks/Doors: 1/1 Rail: No

Acres:

Sprinkler: Yes

Exterior Construction: Split face block and metal Roof: Metal standing seam

Floor Composition:

LISTING:

Comments:

CONTACTS: Colliers Turley Martin Tucker

J. Bart Book, SIOR (317)639-0422

Property Mgmt:

UTILITIES:

Power:

Westfield Gas Gas: Water: **Hamilton County** Sewer: **Hamilton County**

Heat:

AVAILABILITY:

Max. SF Available: 0 Min. SF Available: 0 **Sublease SF Available:**

Owner Company: Storage Solutions

Owner: **Storage Solutions**

Disclaimer: The information contained herein was obtained from sources we consider reliable. We cannot be responsible, however, for errors, omissions, prior sale, withdrawal from the market, or change in price. Seller and broker make no representation as to the environmental condition of the property and recommend purchaser's independent investigation.